

THERMAL UNDERWEAR

Washing and conservation

It can be washed in a washing machine max. 40 degrees but **without spinning**. It is recommended to use special chemicals to clean the outdoor clothing while washing.

Remember! **Ordinary powder is destroying fabrics, from which underwear is made!**

